

Fig. 1A




Fig. 1B




Fig. 2B




Fig. 2B




Fig. 3A







Fig. 3B

Fig. 4




- 2 Wireless Section
- 3 State Detecting Section
- 4 Control Section
- 4a lock Control Section
- 102 Main Operational Operation Section
- 103 Auxiliary Operational Operation Section
- 106 Display Section
- 107a, 107b Speaker
- 108 Microphone

Fig. 5



- | | |
|------|---|
| S501 | Housings are in Open State? |
| S502 | Invalidation of Operation of
Auxiliary Operational Operation Section 103 |
| S503 | Rotation is Detected? |
| S504 | Validation of Operation of
Auxiliary Operational Operation Section 103 |

Fig. 6



- | | |
|------|---|
| S601 | Housings are in Close State? |
| S602 | Validation of Operation of
Auxiliary Operational Operation Section 103 |
| S603 | Rotation is Detected? |
| S604 | Invalidation of Operation of
Auxiliary Operational Operation Section 103 |